


Problem: the *Creader Professional 129 EVO* is changing its MAC-address regularly, which leads to drastic problems with routers in Wi-Fi networks.





Fix: A simple system update will fix this problem. A step-by-step solution follows.




TOPICS:



Service Newsletter | CW38 2020





After this step, the tablet restarts on its own